

**Accessibility Multi-Year Plan (updated April 2018)**  
**Schedule C – Municipal Buildings**

<b>Site</b>	<b>Date Issue Identified</b>	<b>Target</b>	<b>Accessibility Issue</b>	<b>Recommended Action</b>	<b>Responsibility</b>	<b>Completion Date</b>
Baltimore Recreation Centre	2006	On-going (RP)	Canteen-Round tap handles Kitchen-Round tap handles	Replace handles (replacement plan)	Manager, Parks and Recreation	On-going (replacement when required)
Cold Springs Hall	2003		Downstairs Accessible Washroom  -doorway narrow-29"	Widen doorway	Manager of Parks and Facilities	
	2012	Future consideration	No Accessible Washroom on main floor (accessible washroom available downstairs)	Install washroom at time of future renovations		
Shelter of Hope	2011	During expansion	Back door not accessible	To be made accessible during next expansion (JACMSB approval required)		

**Accessibility Multi-Year Plan (updated April 2018)**  
**Schedule C – Municipal Buildings**

<b>Site</b>	<b>Date Issue Identified</b>	<b>Target</b>	<b>Accessibility Issue</b>	<b>Recommended Action</b>	<b>Responsibility</b>	<b>Completion Date</b>
Bewdley Fire Hall	2012	Future consideration	No side door ramp	Add side door ramp with exterior door power accessible opener		
Bewdley Fire Hall	2012	Future consideration	Washroom not accessible	Build accessible washroom with power accessible door  (for public events an accessible port-a-potty may be used outside or in the bay).		
Harwood Fire Hall	2012	Future consideration	No power accessible opener on exterior doors	Add power accessible opener on exterior doors		
Harwood Fire Hall	2012	2014	No concrete or asphalt pads at exterior entrances	Add asphalt pads at exterior entrances		

**Accessibility Multi-Year Plan (updated April 2018)**  
**Schedule C – Municipal Buildings**

<b>Site</b>	<b>Date Issue Identified</b>	<b>Target</b>	<b>Accessibility Issue</b>	<b>Recommended Action</b>	<b>Responsibility</b>	<b>Completion Date</b>
Harwood Fire Hall	2012 *	Future consideration	Washroom not accessible	Build accessible washroom with power accessible door		
Baltimore Fire Hall	2012	2013	Exterior doors not accessible	Add power accessible door opener to exterior doors		
Baltimore Fire Hall	2012	Future consideration	Washroom not accessible	Build accessible washroom with power accessible door		
Baltimore Fire Hall	2012	Future consideration	Second door blocking access	Remove second door – review with Building Official		
Baltimore Fire Hall	2012	Future consideration	No concrete or asphalt pads or ramps at entrances	Build asphalt pads and ramps at east and west doors		

**Accessibility Multi-Year Plan (updated April 2018)**  
**Schedule C – Municipal Buildings**

<b>Site</b>	<b>Date Issue Identified</b>	<b>Target</b>	<b>Accessibility Issue</b>	<b>Recommended Action</b>	<b>Responsibility</b>	<b>Completion Date</b>
Municipal Office	2013	2014	Door to office from lobby not accessible	Replace Door		
Cold Springs Hall	ongoing		Elevator	Regular Inspections as per TSSA	Manager of Parks and Facilities	ongoing
Baltimore Recreation Centre	2017		Indoor Signage - Add Braille as needed	Add Braille as needed	Manager of Parks and Facilities	
Baltimore Recreation Centre	2017		Lights needed for visual signal in case of fire	Put light system in to connect with Fire Alarm	Manager of Parks and Facilities	
Baltimore Recreation Centre	2017		AED sign needs to be out from doorway (more visible)	New signage to be put in place	Manager of Parks and Facilities	
Baltimore Recreation Centre	2017		Access to ice and to Sabic	Push button access	Manager of Parks and Facilities	

**Accessibility Multi-Year Plan (updated April 2018)**  
**Schedule C – Municipal Buildings**

<b>Site</b>	<b>Date Issue Identified</b>	<b>Target</b>	<b>Accessibility Issue</b>	<b>Recommended Action</b>	<b>Responsibility</b>	<b>Completion Date</b>
Baltimore Canteen	2017		Taps are not levered	Install levered taps	Manager of Parks and Facilities	
Cold Springs Hall	2017		Door handle	One door handle missed – needs to be levered.	Manager of Parks and Facilities	
Baltimore Fire Hall	2017		Door Handles	Door handles to be replaced with levered handles	Manager of Parks and Facilities	